ABSTRACT

In a method for forming interlayer connections, metal conducting paths in an overlying layer and vias forming the connections to conducting paths

on an underlying layer are both deposited in one and the same operation. In an interlayer connection formed in this manner the vias are provided integral with connecting conducting paths in the overlying layer.

10 Fig. 3